



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

March 20, 2006

Supervisor *[Signature]*

**Mine Name:** Dolomite Stone  
**Operator Name:** Steven Laub  
8275 South 1975 Road  
Humansville, Missouri 65674

**Permit number:** S/053/050  
**Inspection Date:** March 2, 2006  
**Time:** 2:00 PM

**Inspector(s):** Doug Jensen  
**Other Participants:** None  
**Mine Status:** Inactive

**Weather:** Sunny

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Inspected the site while I was in the area.

#### Inspection Summary:

The road into the site is washed out. I had to walk about a mile and a half into the site from the washed out area.

The site has not changed since I visited the site with Rick Rymerson, BLM, in April of 2004. At that time the site was photographed and GPSd. Because nothing had changed, I did not bother to GPS or take photos of the area.

Volunteer vegetation is beginning to cover the disturbance.

#### Conclusions and Recommendations:

The site is stable and no erosion problems were noted at the time of my visit.

**Inspector's Signature** *[Signature]*

**Date:** 3/20/06

dj:pjb

cc: Steven Laub  
Russ Schreiner BLM, St George FO (UTU-74914)

O:\M053-Washington\S0530050-DolomiteStone\inspections\03022006insp.doc